

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2016

Document Number:

682400954

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	242846	319078	Binschus, Chris	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
PAYNE, RICHARD L.		regulatory@foundationenergy.com	
Allison, Rick		rick.allison@state.co.us	

Compliance Summary:QtrQtr: NWSE Sec: 28 Twp: 8N Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/09/2016	679700147	IJ	IJ	SATISFACTORY			No
06/18/2015	667400691	IJ	IJ	ACTION REQUIRED			No
10/15/2014	667400477	IJ	EI	ACTION REQUIRED			No
09/17/2014	673900503	IJ	AC	SATISFACTORY			No
05/08/2014	667400383	IJ	EI	ACTION REQUIRED			No
07/31/2013	664001166	IJ	AC	SATISFACTORY			No
07/11/2012	663400595	IJ	SI	SATISFACTORY	P		No
05/18/2011	200310581	RT	AC	SATISFACTORY			No
05/03/2010	200246625	RT	AC	SATISFACTORY			No
05/13/2008	200189990	MI	AC	SATISFACTORY			No
04/24/2008	200130644	RT	AC	ACTION REQUIRED			Yes
08/29/2007	200118194	RT	AC	SATISFACTORY			No
06/19/2006	200093892	RT	AC	SATISFACTORY		Pass	No
06/28/2005	200073230	MI	AC	SATISFACTORY		Pass	No
02/25/2004	200050548	RT	AC	SATISFACTORY		Pass	No
04/15/2003	200037611	RT	AC	SATISFACTORY		Pass	No
08/01/2002	200029319	RT	AC	SATISFACTORY		Pass	No
07/15/2002	200028885	PR	PR	ACTION REQUIRED		Fail	Yes
08/21/2001	200019168	RT	AC	SATISFACTORY		Pass	No

Inspector Name: Binschus, Chris

06/29/2000	200008065	MI	AC	SATISFACTORY		Pass	No
06/27/2000	200008058	MI	AC	SATISFACTORY		Fail	No
03/14/1995	500165875	MI	AC			Pass	No

Inspector Comment:

This was a joint Final Reclamation inspection with COGCC Environmental and Reclamation staff regarding two separate flowline release areas associated with remediation sites. Per Field Inspection Report Document #679700190, Remediation Project #8518 and #8550 will remain open until compliance with Rule 1004 regarding surface reclamation. See Final Reclamation section and COGCC comments for additional information regarding current reclamation status of this location. This inspection only applies to the above mentioned flowline release areas associated with Remediation Project #8518 and #8550.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
242846	WELL	IJ	09/16/2007	ERIW	123-10637	SOONER UNIT 10-28	RI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:			
Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 242846

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspector Name: Binschus, Chris

Facility

Facility ID: 242846 Type: WELL API Number: 123-10637 Status: IJ Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed?

CM
CA CA Date

Unused or unneeded equipment onsite?

CM
CA CA Date

Pit, cellars, rat holes and other bores closed?

CM
CA CA Date

Guy line anchors marked?

CM
CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

Inspector Name: Binschus, Chris

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: See COGCC comments for current reclamation status.

Corrective Action: _____ Date _____

Overall Final Reclamation In Process Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>Remediation Site #8518: IN PROCESS- The release area is dominated by Cheatgrass (Bromus tectorum) which is an undesirable plant species and considered a List C Colorado Noxious weed. Stormwater BMPs have been installed along the down gradient slope. Vegetation, whether it is desirable or not (i.e., cheatgrass), appears to be stabilizing the slope. Location will be inspected on a future date to determine vegetative composition and ensure compliance with Rule 1004.</p> <p>Remediation Site #8550: IN PROCESS- Need to maintain fence to ensure cattle does not negatively affect the reclamation process.</p> <p>Refer to attached photos in Document #682400955.</p>	binschusc	07/12/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682400955	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3901852