

Final Reclamation Inspection- Flowline Release Area



Photo 1. Photo taken from east of release area, facing South. Reclamation is IN PROCESS. Location has been seeded and vegetation appears to be establishing.

Final Reclamation Inspection- Flowline Release Area



Photo 2. Photo taken from east of release area, facing North. Reclamation is IN PROCESS. Location has been seeded and vegetation appears to be establishing.