



Photo#1: Location Sign at Entry.



Photo#2: Location site is at top of 300Ft of Fill from Road Construction.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#3: Entry into Helipad/ Muster area. Location center to East of vehicles , noted by Arrow.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#4: : View over Location Center to North. Cellar and Liner Visible , indicated by Dash line.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#5: : View over Location Center to South.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#6: View over Location Center to East.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#7: View over Location Center to West.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#8: Gravel & remnants of Liner on Location.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#9: Guy Anchor not removed.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#10: Flow lines or other Facility ? to be identified as related to Location or to other uses of Area.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#11: View to West along Fill Slope ditch and Berm at South edge of Location

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#12: Vegetation establishing in heavily graveled portions of Location predominately Rabbit Brush and Clover.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016



Photo#13: Rabbit Brush establishing in Rocky Fill Material.

Inspection Photos: Exxon Mobil PA API#045-14231

July 7, 2016