



Photo 1. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Possible pit subsidence where dark vegetation is growing in left hand side of photo.



Photo 3. View of bare area on well pad where it appears tanks have been removed.



Photo 4. View of debris that needs to be removed.



Photo 5. View of musk thistles in southern portion of the project area.



Photo 6. View of cement debris on well pad area.



Photo 7. View of the beginning of Transect 1, on well pad, facing eastward.



Photo 8. Birdseye vies of vegetation present at mid-point along Transect 1, within the project area.



Photo 9. View of the beginning of Transect 2, reference area transect, located north of the project area, facing eastward.



Photo 10. Birdseye view of vegetation at midpoint along reference area transect.



Photo 11. Another view of vegetation along reference area transect, from midpoint to end, facing eastward.