



Photo 1. View of the project area from the beginning of the access road foacing southward. Well pad has been reclaimed and straw mulch has been crimped.



Photo 2. View from the wellhead facing southward.



Photo 3. View from the wellhead facing eastward.



Photo 4. View of musk thistles around the edge of the project area.



Photo 5-7. View of small pieces of debris scattered around the well pad.

