



Photo#1: Overview of Location from Entry to NW.

July 7, 2016

Inspection Photos: LINN Loc#335673



Photo#2: Overview of Location from West end to SE.

Inspection Photos: LINN Loc#335673

July 7, 2016





Photo#3: View of Well Corral with Six Cellars, Conductors Set.

Inspection Photos: LINN Loc#335673

July 7, 2016



Photo#4: Interim Reclamation Fill Slope , view to West.

Inspection Photos: LINN Loc#335673

July 7, 2016





Photo#5: Interim Reclamation Area Fill Slope ,Vegetation well established..

Inspection Photos: LINN Loc#335673

July 7, 2016



Photo#6: View to West of Interim Reclamation, Ditch and small Berm running along base of Fill Slopes.

Inspection Photos: LINN Loc#335673

July 7, 2016