

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2016

Document Number:

680600805

Overall Inspection:

SATISFACTORY w/ CMT
or AR

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>214516</u>	<u>325301</u>	<u>ROY, CATHERINE</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number:	<u>56680</u>
Name of Operator:	<u>MERRION OIL & GAS CORP</u>
Address:	<u>610 REILLY AVENUE</u>
City:	<u>FARMINGTON</u> State: <u>NM</u> Zip: <u>87401</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

Compliance Summary:

QtrQtr: SWNW Sec: 6 Twp: 33N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/01/2011	200315734	CA	PA	SATISFACTORY			No
02/18/2010	200231624	ID	SI	SATISFACTORY			No
11/23/2009	200222557	ID	SI	SATISFACTORY			No
03/01/2009	200206432	PR	PR	SATISFACTORY			No
11/07/2008	200198187	PR	PR	SATISFACTORY			No
06/20/2007	200120544	PR	PR	SATISFACTORY			No
06/01/2006	200090836	CC	WO	SATISFACTORY		Pass	No
05/30/2006	200090835	CA	PA	SATISFACTORY		Pass	No
03/27/2006	200087513	ID	TA	ACTION REQUIRED		Fail	Yes
02/09/2000	200004343	ID	TA	SATISFACTORY		Pass	No
02/04/1998	500147470	ID	TA			Pass	No
01/23/1998	500147469	ID	TA			Pass	No
03/13/1996	500147468	ID	TA				No

Inspector Comment:

This is a final reclamation inspection. Our records (Doc 2588074) indicate this well was plugged and abandoned on July 6, 2011.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
214516	WELL	PA	07/06/2011	GW	067-06119	BARNES 1	RI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 214516

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 214516 Type: WELL API Number: 067-06119 Status: PA Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____
 Reminder: _____

Comment: **Project area is surrounded by irrigated pasture. Revegetation is progressing slowly within the project area. As determined during a vegetation transect, revegetation is 12 percent of a nearby reference area vegetation. Cows were grazing on location and reference area during the inspection. See attached photos and transect datasheet.**

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed Pass No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured In
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present In Process Subsidence _____
 Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____

Comment: **Stormwater erosion is controlled on the location.**

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Overall this inspection is "Satisfactory". However revegetation is only 12 percent of the reference area. Revegetation needs to be monitored and if cover is not increasing over time, then additional revegetation and soil reclamation measures may be needed.	RoyC	07/20/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680600806	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3907732
680600807	Transect Datasheet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3907733