



Photo 1. Photo taken of PR well sign for API #001-06321.

Stormwater Inspection



Photo 2. Photo taken from well location, facing East, along the access road. Rills from erosion along the access road have been fixed.

Stormwater Inspection



Photo 3. Photo taken from the southern well location, facing West, toward the first BMP. Two stormwater BMPs installed along the southern location to control stormwater and transport of sediment.

Stormwater Inspection



Photo 4. Photo taken from the southern well location, facing West, toward the second BMP. Two stormwater BMPs installed along the southern location to control stormwater and transport of sediment.

Stormwater Inspection



Photo 5. Photo taken from southwest of well location, facing North. Gully from erosion has been filled in.

Stormwater Inspection



Photo 6. Photo taken from southwest of well location, facing South. Gully from erosion has been filled in.