


# Final Reclamation Inspection



**Photo 1.** Photo taken from center of location, facing West. Vegetative growth appears to be reflective of reference areas. A number of native, perennial grass species were observed throughout location. However, location was not recontoured and 3 guy line anchors were left behind.


# Final Reclamation Inspection



**Photo 2.** Photo taken from center of location, facing North. Vegetative growth appears to be reflective of reference areas. A number of native, perennial grass species were observed throughout location. However, location was not recontoured and 3 guy line anchors were left behind.



# Final Reclamation Inspection



**Photo 3.** Photo taken from center of location, facing East. Vegetative growth appears to be reflective of reference areas. A number of native, perennial grass species were observed throughout location. However, location was not recontoured and 3 guy line anchors were left behind.

# Final Reclamation Inspection



**Photo 4.** Photo taken from center of location, facing North. Vegetative growth appears to be reflective of reference areas. A number of native, perennial grass species were observed throughout location. However, location was not recontoured and 3 guy line anchors were left behind.