

Final Reclamation Inspection



Photo 1. 2015 aerial imagery using COGCC GISOnline database, illustrating the well location and tank battery location where equipment remains.

Final Reclamation Inspection



Photo 2. Photo taken of equipment which needs to be removed and reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing West. Vegetative plant cover is not consistent throughout area. Large areas have no plant growth. Evidence of seeding is noticeable.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing North. Vegetative plant cover is not consistent throughout area. Large areas have no plant growth as shown with this photo. Evidence of seeding is noticeable.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing East. Vegetative plant cover is not consistent throughout area. Large areas have no plant growth as shown with this photo. Evidence of seeding is noticeable.

Final Reclamation Inspection



Photo 6. Photo taken from center of location, facing North. Vegetative plant cover is not consistent throughout area. Evidence of seeding is noticeable.

Final Reclamation Inspection



Photo 7. Photo taken from approximate center of location, facing West. Large areas have no plant growth as shown with this photo.

Final Reclamation Inspection



Photo 8. Photo taken from approximate center of location, facing South. Large areas have no plant growth as shown with this photo. Evidence of seeding is noticeable but no plant growth.