

Final Reclamation Inspection



Photo 1. 2015 aerial imagery using COGCC GISOnline database, illustrating total areas that have not been reclaimed.

Final Reclamation Inspection



Photo 2. Photo taken from west of well location, facing East. Well location has not been properly reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from northern tank battery location, facing South. Evidence of seeding is noticeable. However, gravel remains and compaction alleviation was not completed making near impossible for anything to grow.

Final Reclamation Inspection



Photo 4. Photo taken from northern tank battery location, facing Southwest. Evidence of seeding is noticeable. However, gravel remains and compaction alleviation was not completed making near impossible for anything to grow.

Final Reclamation Inspection



Photo 5. Photo taken from the central tank battery location, facing West. Evidence of seeding is noticeable. However, gravel remains and compaction alleviation was not completed making near impossible for anything to grow.

Final Reclamation Inspection



Photo 6. Photo taken from tank battery entrance. Need to remove cattle guard equipment.

Final Reclamation Inspection



Photo 7. Reference photo taken north of well location.