

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Uniform vegetative growth throughout location. Vegetative growth at location appears to be reflective or reference areas.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Uniform vegetative growth throughout location. Vegetative growth at location appears to be reflective or reference areas.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Uniform vegetative growth throughout location. Vegetative growth at location appears to be reflective or reference areas.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Uniform vegetative growth throughout location. Vegetative growth at location appears to be reflective or reference areas.

Final Reclamation Inspection



Photo 5. Close up photo from approximate center of location.

Final Reclamation Inspection



Photo 6. Reference photo taken approximately 300 feet west of location, facing Southwest.

Final Reclamation Inspection



Photo 7. Close up reference photo taken from previous photo location.