



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern portion of the project area facing southward. Weeds within the fenced area have largely been treated.



Photo 3. View of infestation of approximately 1000 Canada thistle (*Cirsium arvense*) outside of the northern fenceline, but still within the project disturbance.



Photo 4. View of cobble run-down BMP and tall flowering musk thistles (*Carduus nutans*) outside of the fence but within the project disturbance in the northwestern corner.



Photo 5. View of large flowering and seeding musk thistles in the western portion of the project area outside of the fence.



Photo 6. View of the access road near the well pad entrance facing eastward. Thousands of musk thistle are growing along the access road and need to be controlled.