



Photo#1: Access Road Entry into Location ; Blooming Musk Thistle lining Road.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12



Photo#2: Overview of Location to SE; showing Cut Slope Sloughing /Riling/Channeling SW Concerns.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12





Photo#3: View of one Sloughed area of Cut Slope.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12



Photo#4: View showing entry point of water causing erosion Channel of sloughed Cut Slope.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12





Photo#5: View of Cut Slope Riling, Channeling and Sediment run –On.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12



Photo#6: Seep at base of Cut Slope.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12





Photo#7: Drain at SW corner at base of Fill deeply into ditch that drains to settlement Pond to NW.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12



Photo#8: Houndstongue and Musk thistle populating Fill Slope.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12





Photo#9: Houndstongue is setting Seed.

July 24, 2016

Inspection Photos: TEP Loc# 413683 Youberg SR 43-12