



Photo#1: Over view of Location from Entry.

July 24, 2016

Inspection Photo: Laramie Hooker Loc#335165



Photo#2: Overview of Wells

July 24, 2016

Inspection Photo: Laramie Hooker Loc#335165



Photo#3: Fenced Interim Reclamation area on East side of Location.

July 24, 2016

Inspection Photo: Laramie Hooker Loc#335165



Photo#4: Interim Reclamation Vegetation establishing well in Fill Slope area.

July 24, 2016

Inspection Photo: Laramie Hooker Loc#335165