

Construction Inspection



Photo 1. Photo taken from western location, facing South towards topsoil stockpile. Need to stabilize topsoil stockpile upon completion of salvage operations. Unconsolidated berms along perimeter of location need to be compacted.

Construction Inspection



Photo 2. Photo taken from southwest location, facing East. Need to stabilize topsoil stockpile upon completion of salvage operations. Unconsolidated berms along perimeter of location need to be compacted.

Construction Inspection



Photo 3. Photo taken from southeast location, facing North. Unconsolidated berms along perimeter of location need to be compacted.

Construction Inspection



Photo 4. Photo taken from northeast location, facing West. Unconsolidated berms along perimeter of location need to be compacted.