

Final Reclamation Inspection

08/03/2016

Operator: Oilfield Salvage & Service #65550

Location ID: 311709

Washington County, CO

NWSE Section 18 T3S R58W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Figure 2: Photo taken from the south end of the location. Photo shows large hole on location, likely same hole identified in inspection doc. #200089436



Figure 3: Photo shows large hole found on location is approximately 2 feet deep.



Figure 4: Photo shows large hole found on location is approximately 2 feet deep.



Figure 5: Photo shows width of hole on location. 6' measuring stick for reference.



Figure 6: Photo taken from the east end of the location, facing west. Photo shows vegetation over the reclamation area. 6' measuring stick for reference.



Figure 7: Photo taken from the east end of the location, facing west. Photo shows vegetation over the reclamation area. 6' measuring stick for reference.



Figure 8: Photo taken from the south end of the location, facing southeast. Photo shows large un-vegetated area experiencing erosion. Area the result of a produced water spill. 6' measuring stick for reference.



Figure 9: Photo taken from the south end of the location, facing south. Photo shows large un-vegetated area experiencing erosion. Area the result of a produced water spill. 6' measuring stick for reference.



Figure 10: Photo taken from the south end of the location, facing south. Photo shows degradation caused by stormwater erosion over spill area.



Figure 11: Photo taken from the south end of the spill area, facing north. Photo shows degradation caused by stormwater erosion over spill area.



Figure 12: Photo taken from the south end of the spill area, facing north. Photo shows degradation caused by stormwater erosion over spill area.



Figure 13: Photo taken from the south end of the spill area, facing north. Photo shows degradation caused by stormwater erosion over spill area.



Figure 14: Photo taken from the south end of the spill area, facing north. Photo shows degradation caused by stormwater erosion over spill area.