

Federal 4-35

Inspection# 673403472

Low berm with weeds growing on and in it. Tank label missing capacity.



Ruts in access road. Hard hat for scale.



Ruts in access road. Hard hat for scale.



Ruts in access road. Hard hat for scale. Drainage crossing in background.



On opposite side of drainage from previous picture.



Evidence of sediment entering drainage at road crossing.

