



photo 1: Northwest side of the location facing south, west side of the road.



photo 2: There is an erosion channel at the northwest side of the location from stormwater directed from the access road.



photo 3: Southwest side of the location facing north, west side of the road.



photo 4: Facing north toward the main road which splits the location in half.



photo 5: Southeast side of the location facing north, east side of the road.



photo 6: There is an erosion channel at the southeast side of the location from stormwater directed from the access road.



photo 7: Northeast side of the location facing southwest.



photo 8: Northeast side of the location facing west.