

# Final Reclamation Inspection

08/05/2016

Operator: Markus Production inc.

Location ID: 406198

Weld County, CO

SESE Section 36 T8N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



12307977	07° W
12313350	0.31° NW
12312579	0.51° E
12312578	0.51° SE
12309430	0.51° W

08.05.2016 15:07

**Figure 1:** Photo of GPS confirming location.



**Figure 2:** Photo of the starting point for the disturbance transect, facing north.



**Figure 3:** Photo of vegetation at the 50th point of the disturbance transect, facing west.



**Figure 4:** Photo of vegetation at the 50th point of the disturbance transect, facing east.



**Figure 5:** Photo of vegetation at the 50th point of the disturbance transect.



**Figure 6:** Photo of the end point for the disturbance transect, facing south.



**Figure 7:** Photo of the starting point for the reference transect, facing east



**Figure 8:** Photo of vegetation at the 50th point of the reference transect, facing north.



**Figure 9:** Photo of vegetation at the 50th point of the reference transect, facing south.



**Figure 10:** Photo of vegetation at the 50th point of the reference transect.



**Figure 11:** Photo of the end point for the reference transect, facing west.



**Figure 12:** Photo taken from the southeast corner of the location, facing north. Photo shows vegetation over the reclamation area. Note vegetation has not achieved uniform cover.



**Figure 13:** Photo taken from the southeast corner of the location, facing west. Photo shows vegetation over the reclamation area. Note vegetation has not achieved uniform cover.



**Figure 14:** Photo taken from the southwest corner of the location, facing east. Photo shows vegetation over the reclamation area. Note vegetation has not achieved uniform cover.



**Figure 15:** Photo taken from the southwest corner of the location, facing north. Photo shows vegetation over the reclamation area. Note vegetation has not achieved uniform cover.



**Figure 16:** Photo taken from the northwest corner of the location, facing south. Photo shows vegetation over the reclamation area.



**Figure 17:** Photo taken from the northwest corner of the location, facing east. Photo shows vegetation over the reclamation area. Note vegetation area in the northeast corner experiencing erosion.



**Figure 18:** Photo taken from the northeast corner of the location, facing east. Photo shows vegetation over the reclamation area. Note area experiencing erosion.



**Figure 19:** Photo taken from the northeast corner of the location, facing south. Photo shows vegetation over the reclamation area. Note area experiencing erosion.