



Photo#1: View to North of Location from Entry.

August 11, 2016

Inspection Photos: Mustang PR API# 045-06567 : Complaint



Photo#2: View over Location to South.

Inspection Photos: Mustang PR API# 045-06567 : Complaint

August 11, 2016



Photo#3: Field of Concern adjacent and SW of Location.

Inspection Photos: Mustang PR API# 045-06567 : Complaint

August 11, 2016



Photo#4: Water body of concern to NW of Location.

Inspection Photos: Mustang PR API# 045-06567 : Complaint

August 11, 2016



Photo#5: Interim Vegetation consists mainly of Crested Wheat Grass..

Inspection Photos: Mustang PR API# 045-06567 : Complaint

August 11, 2016



Photo#6: View of Guy Anchor at NW corner of Location, showing some Russian thistle (Noxious Weed) has emerged and matured in this area.

Inspection Photos: Mustang PR API# 045-06567 : Complaint

August 11, 2016