

## Location ID 438023- Follow up inspection



**Photo 1.** Photo taken from the western flowline area, facing East. Flowline area was mowed and bagged to remove longspine sandbur.