

# Construction and Stormwater Inspection

08/17/2016

Operator: Grand Mesa Operating

Location ID: 445661

Washington County, CO

NESW Section 18 T5S R53W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo taken from the southwest corner of the location, facing north. Photo shows stormwater and sediment control ditch.



**Figure 2:** Photo taken from the southwest corner of the location, facing east. Photo shows stormwater and sediment control ditch.



**Figure 3:** Photo taken from the southeast corner of the location, facing east. Photo shows stormwater and sediment control ditch.



**Figure 4:** Photo taken from the southeast corner of the location, facing north. Photo shows stormwater and sediment control ditch. Some sections of the ditch appear to be filling with sediment, advise cleaning in these areas.



**Figure 5:** Photo taken from the east end of the location, facing north. Photo shows stormwater and sediment control ditch. Some sections of the ditch appear to be filling with sediment, advise cleaning in these areas.



**Figure 6:** Photo taken from the east end of the location, facing west. Photo shows stormwater and sediment control ditch. Some sections of the ditch appear to be filling with sediment, advise cleaning in these areas.



**Figure 7:** Photo taken from the northeast end of the location, facing south. Photo shows stormwater and sediment control ditch.



**Figure 8:** Photo taken from the northeast end of the location, facing west. Photo shows stormwater and sediment control ditch.



**Figure 9:** Photo taken from the northwest end of the location, facing south. Photo shows stormwater and sediment control ditch. Ditch ends before corner of location. This area is at higher risk of seeing stormwater and sediment transport off site and degradation. Advise incorporating other BMPs or connecting ditch.



**Figure 10:** Photo taken from the northwest end of the location, facing south. Photo shows stormwater and sediment control ditch. Ditch ends before corner of location. This area is at higher risk of seeing stormwater and sediment transport off site and degradation. Advise incorporating other BMPs or connecting ditch.



**Figure 11:** Photo taken from the northwest corner. Photo shows an elevated ditch/berm constructed in corner.