



**photo 1:** Facing northeast along the access road where erosion issues were repaired.



**photo 2:** Facing east toward the location.



**photo 3:** Facing southeast at the location where erosion issues were repaired.



**photo 4:** The Canada thistle noticed in the previous inspection has been removed.



**photo 5:** Facing west toward the location.



**photo 6:** Facing south along the access road where erosion issues were repaired.