



photo 1: Access road near the location, erosion issues has been repaired.



photo 2: Facing southeast toward the location.



photo 3: North side of the location facing south.



photo 4: The south slope has been hydro mulched/seeded and a berm has been installed.