

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API 123-13177. Emergency contact on sign is not legible and not complete.

Interim Reclamation Inspection



Photo 2. Photo taken from central location, facing Southwest. Control weeds around all equipment at location. Weeds within 25 feet of operating oil and gas equipment are a potential safety or fire concern per Rule 603.f.

Interim Reclamation Inspection



Photo 3. Photo taken from northwestern location, facing South. Control weeds around all equipment at location. Weeds within 25 feet of operating oil and gas equipment are a potential safety or fire concern per Rule 603.f.