



Photo 1. View of riser still in place near the entrance to the well pad.



Photo 2. View of culvert in place at the entrance to the well pad.



Photo 3. View of yellow toadflax growing in the southern cutslope of the well pad.



Photo 4. View of spotted knapweed growing throughout the project area.



Photo 5. View of the western portion of the project area from the northwestern corner facing southward.



Photo 6. View from the northwestern corner of the well pad facing center.



Photo 7. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 8. View of the eastern portion of the well pad from the northeastern corner facing southward.



Photo 9. Pit area in northeastern portion of project area has not been recontoured.



Photo 10. View of access road from near the access entrance facing northward.