



Photo 1. View at the entrance to the access road facing eastward. Access road has not been reclaimed.



Photo 2. View of pipeline riser south of the access road that needs to be removed or documentation provided showing that it is in use.



Photo 3. View of musk thistles (*Carduus nutans*) growing around the pipeline riser.



Photo 4. View of another riser that needs to be removed south of the project area.



Photo 5. View of the northeastern portion of the project area from the northern corner facing southeastward. The majority of the well pad is devoid of vegetation.



Photo 6. View from the northern corner of the project area facing center.



Photo 7. View of the northern portion of the project area from the northern corner facing westward.



Photo 8. View from the approximate wellhead facing northward.



Photo 9. View of soil piles, unclear if this is topsoil (?) in the southeastern portion of the project area.