

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2016

Document Number:

674602750

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	242860	319086	Maclaren, Joe	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Dodek, Brian	720-225-6653	BDodek@bonanzacrk.com	
Hazard, Ellice		ellice.hazard@state.co.us	
Allison, Rick		rick.allison@state.co.us	
,		EHSRC@bonanzacrk.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Compliance Summary:

QtrQtr:	NWNW	Sec:	23	Twp:	5N	Range:	61W
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/09/2016	679700213	PR	EI	SC			No
04/26/2013	670500949	PR	PR	ACTION REQUIRED	Pass		No
02/18/2011	200297021	PR	PR	ACTION REQUIRED			Yes
06/09/2003	200040111	PR	PR	SATISFACTORY		Pass	No
10/21/2002	200031845	PR	PR	SATISFACTORY		Fail	Yes
04/01/1996	500165899	PR	PR			Pass	No

Inspector Comment:

COGCC Integrity Inspection performed on August 24th, 2016 in response to initial form 19 spill report Doc #401095189 received by COGCC on 08/17/2016 that outlines the following: During flowline pressure testing, a historical release was discovered adjacent to the heater treater at the Wildfong 11-23 tank battery. A prior release was also reported to COGCC doc #401086924 on 8/1/2016 that states: A flowline release of approximately 5 gallons of oil surfaced above a flowline adjacent to the Wildfong 11-23 wellhead. The release occurred at a buried fitting. The equipment/ flowline section of this report has details of observations made during this field inspection. Photo's uploaded can be accessed via link(s) at end of report. Note: The Actions Required outlined on the previous environmental inspection doc #679700213 performed on 08/09/2016 must be completed as outlined.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
242860	WELL	PR	01/01/2014	OW	123-10651	WILDFONG 11-23	EG	<input checked="" type="checkbox"/>

Inspector Name: Maclaren, Joe

447095	SPILL OR RELEASE	AC	08/12/2016	-	SPILL/RELEASE POINT	AC	
--------	---------------------	----	------------	---	---------------------	----	--

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT		Site equipment, including separator, pump jack, ECD, and production tanks, moved and unused due to spill remediation activities.		

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 3	Satisfactory/Action Required: SATISFACTORY
Comment	COGCC Inspector met with contractor personnel (Shale Stone Resources) on location. The fiberglass flowline between the wellhead and separator is scheduled for replacement. The oil and water dump flowlines were flushed and pressure tested (will be reused). (3) historic abandoned flowlines were encountered, left in place next to dump lines, flushed and capped. Cleanup and site remediation activities are in progress.	
Corrective Action		Date:

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 242860

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 242860 Type: WELL API Number: 123-10651 Status: PR Insp. Status: EG

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Inspector Name: Maclaren, Joe

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: Maclaren, Joe

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Note: Conduct pressure testing of all new and repaired flowlines prior to returning to service (integrity confirmation) and maintain records/ charts in house.	maclarej	08/26/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602756	Well Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3937983
674602757	Excavation/ remediation and exposed flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3937984
674602758	Exposed dump and historic abandoned flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3937985