

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/25/2016
Document Number:
674602753
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>240812</u>	<u>318184</u>	<u>Maclaren, Joe</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>47120</u>
Name of Operator:	<u>KERR MCGEE OIL & GAS ONSHORE LP</u>
Address:	<u>P O BOX 173779</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@anadarko.com	All inspections
Avant, Paul		paul.avant@anadarko.com	Include on Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Reddy, Luke		luke.reddy@anadarko.com	All Inspections

Compliance Summary:

QtrQtr: SWSW Sec: 2 Twp: 1N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/08/2013	667601042	PR	TA	SATISFACTORY	In Process		No
09/07/2010	200277588	PR	PR	ACTION REQUIRED			Yes
01/23/1999	500163011	PR	PR			Pass	No
08/20/1997	500163010	PR	PR				
09/28/1994	500163009		PR			Pass	No

Inspector Comment:

COGCC Interity Inspector Joe MacLaren met with Anadarko Construction Supervisor Mark Grage and ECS Mike Albright on 8/25/2016 and performed a flowline (abandonment) field inspection. This well (API 123-08600) is currently being plugged and abandoned. The flowline section of this report outlines details of the observations made during this field inspection. Photo's uploaded can be accessed via link(s) at end of report.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240812	WELL	PR	02/12/1998	GW	123-08600	PHILLIP CAMENISCH GAS UNIT 1	EG <input checked="" type="checkbox"/>
426147	WELL	AL	03/28/2012	LO	123-34594	CAMENISCH 12-2	AL <input type="checkbox"/>
426154	WELL	PR	06/12/2013	GW	123-34595	CAMENISCH 11-2	PR <input type="checkbox"/>
426159	WELL	PR	06/12/2013	GW	123-34597	CAMENISCH 25-2	PR <input type="checkbox"/>

Inspector Name: Maclaren, Joe

426165	WELL	PR	06/12/2013	GW	123-34599	CAMENISCH 32-2	PR	
426166	WELL	PR	06/12/2013	GW	123-34600	CAMENISCH 22-2	PR	
426167	WELL	PR	06/12/2013	GW	123-34601	CAMENISCH 23-2	PR	
426175	WELL	PR	06/12/2013	GW	123-34602	CAMENISCH 36-2	PR	
443577	TANK BATTERY	AC	06/12/2013		-	CAMENISCH 36-2	AC	
443578	TANK BATTERY	AC	06/12/2013		-	CAMENISCH 36-2	AC	

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type: Flow Line	# 2	Satisfactory/Action Required: SATISFACTORY
Comment:	The 2" (carbon steel) well site flowline between wellhead and separator (and 1" gas supply line) have been properly abandoned. The lines run in close proximity to other active well site flowlines (multi well pad). The flowline(s) were flushed, disconnected, cut 5' below grade and plugged. A GPS marker ball was placed to obtain coordinates of endpoint of abandoned lines. The flowline risers at the separator (common with other wells) were disconnected and marked. Note: The well casing was also cut, labled and capped. This area is scheduled to be backfilled and reclaimed.	
Corrective Action:	Date:	

Venting:

Yes/No	
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 240812

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 240812 Type: WELL API Number: 123-08600 Status: PR Insp. Status: EG

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: Maclaren, Joe

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602760	Well Sign (showing PA status)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3938020
674602761	Well Casing being cut & removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3938021
674602762	Plugged well with cap (to be buried)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3938022
674602763	Abandoned flowline (with GPS marker ball in place)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3938023