



**photo 1:** Facing east along the access road toward the location. Compressor equipment in the upper left of the photo.



**photo 2:** Facing east along the access road toward the location.



**photo 3:** Tank battery remains near the west side of the location.



**photo 4:** Facing west toward the tank battery. Unused equipment which was in this area has been removed.



**photo 5:** Facing east toward the location.



**photo 6:** Pipe riser remains at the center of the location. Lat/Long:37.95992,-102.50066



**photo 7:** East side of the location facing west. Undesirable weed growth noticed throughout the location.



**photo 8:** Facing east at center of the location. Undesirable weed growth noticed throughout the location.



**photo 9:** West side of the location facing east.



**photo 10:** Facing south toward the surrounding undisturbed pasture (reference area). There is no undesirable vegetation found in this area outside of the location.