



photo 1: Facing south toward the location.



photo 2: Center of the location facing south. Vegetation has not established in this area. The soils seemed to be compacted and there is gravel that remains.



photo 3: View of groundcover at the center of the location. Vegetation has not established in this area. The soils seemed to be compacted and there is gravel that remains.



photo 4: South side of the location facing north. The pipe riser has not been removed.



photo 5: West side of the location facing southeast. The pipe riser remains at the west side of the location.



photo 6: Northeast side of the location facing east. Vegetation has not established in this area.



photo 7: View of the ground cover at the northeast side of the location. Vegetation has not established in this area.



photo 8: Facing south toward the surrounding undisturbed pasture (reference area).