

Final Reclamation Inspection



Photo 1. Photo taken from entrance of location, facing West. Large portions have no native, perennial vegetative growth as shown with this photo.

Final Reclamation Inspection



Photo 2. Photo taken from entrance of location, facing East. Large portions have no native, perennial vegetative growth as shown with this photo. Majority of vegetative growth are weedy, annual plants.

Final Reclamation Inspection



Photo 3. Photo taken from entrance of location, facing North. Large portions have no native, perennial vegetative growth as shown with this photo. Majority of vegetative growth are weedy, annual plants. Equipment remains at location and a well release will not be granted until all equipment is removed.

Final Reclamation Inspection



Photo 4. Photo taken from the northern location, facing North. Vegetative growth appears to be establishing along northern the location.

Final Reclamation Inspection



Photo 5. Reference photo taken north of location illustrating native, perennial vegetative growth.