

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing North. Location has not been reclaimed per Rule 1004. Little to no perennial vegetative growth has established at location. Weedy, annual vegetation dominates location which is not reflective or reference areas.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing East. Location has not been reclaimed per Rule 1004. Little to no perennial vegetative growth has established at location. Weedy, annual vegetation dominates location which is not reflective or reference areas.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing South. Location has not been reclaimed per Rule 1004. Little to no perennial vegetative growth has established at location. Weedy, annual vegetation dominates location which is not reflective of reference areas.

Final Reclamation Inspection



Photo 4. Reference photo taken south of location, facing South. Vegetative growth does not appear to be reflective of reference areas.

Final Reclamation Inspection



Photo 5. Photo taken from western location, facing East. A List B Colorado Noxious weed species, Musk thistle (*Carduus nutans*), appears to have been sprayed at location.