



photo 1: Facing north along the access road. The side of the access road was recently seeded and hydro-mulched.



photo 2: Facing east toward the location.