

Foundation Overview- Diffuse knapweed (*Centarea diffusa*)


3 Locations Inspected:

Krager Sites

- 1) Location 331849- Portions mowed and knapweed was observed in the cuttings and a handful of individual Diffuse knapweeds left behind. Foundation instructed on 8/25/16 to pull and bag remaining plants. Foundation instructed on 8/30/16 to collect, remove, and dispose weed debris and seed heads properly from areas that were mowed.
- 2) Tank battery/storage yard- Portions mowed and knapweed was observed in the cuttings and several patches, varying in size, of Diffuse knapweed left behind. Foundation instructed on 8/25/16 to pull and bag remaining plants. Foundation instructed on 8/30/16 to collect, remove, and dispose weed debris and seed heads properly from areas that were mowed.

Sooner Unit- Location ID 447525

- 3) Southern Tank battery was mowed. Knapweed was observed in the cuttings and only a handful of individual knapweeds left behind. Foundation instructed on 8/25/16 to pull and bag remaining plants. Foundation instructed on 8/30/16 to collect, remove, and dispose weed debris and seed heads properly from areas that were mowed.



Sooner Unit- Southern Tank battery (Location ID 447525)




Photo 1. Photo taken from entrance of location, facing West. Location was mowed within the last 2 days based off conversations with other COGCC staff. Complainant has pulled and bagged Diffuse knapweed from this location. A handful of individual Diffuse knapweeds left behind. Diffuse knapweed seed heads were observed in the mowed cuttings.

Sooner Unit- Southern Tank battery (Location ID 447525)



Photo 2. Photo taken from southwest location, facing North. Location was mowed within the last 2 days based off conversations with other COGCC staff. Complainant has pulled and bagged Diffuse knapweed from this location. A handful of individual Diffuse knapweeds left behind were observed along the western area.