



photo 1: Facing northeast at the beginning of the former access road.



photo 2: Facing northeast along the former access road.



photo 3: Facing northeast further along the former access road.



photo 4: Facing north toward the location.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: The soils were checked for compaction along the access road. There were areas that seemed to be compacted.



photo 10: Facing east toward the surrounding undisturbed pasture.