



Photo 1. View from the dry hole marker facing northward.



Photo 2. View from the dry hole marker facing eastward.





Photo 3. View from the dry hole marker facing westward.





Photo 4. View of metal debris in the project area.





Photo 5. View of more metal debris in the project area.





Photo 6. View of erosional downcutting and metal debris in the project area.