

# Final Reclamation Inspection



**Photo 1.** Photo taken of well sign at approximate center of well location.

# Final Reclamation Inspection



**Photo 2.** Photo taken from approximate center of location, facing West. Perennial vegetation has established at location but an area lacks vegetative growth. See Photos 6 and 7.

# Final Reclamation Inspection



**Photo 3.** Photo taken from approximate center of location, facing North. Perennial vegetation has established at location but an area lacks vegetative growth. See Photos 6 and 7.

# Final Reclamation Inspection



**Photo 4.** Photo taken from approximate center of location, facing East. Perennial vegetation has established at location but this area lacks vegetative growth. Refer to photos 6 and 7.

# Final Reclamation Inspection



**Photo 5.** Photo taken from the western location. Need to remove all debris from location, if this is from oil and gas operations.

# Final Reclamation Inspection



**Photo 6.** Photo taken from the eastern location. Location lacks any vegetative growth where it would appear the wellhead may have been.

# Final Reclamation Inspection



**Photo 7.** Photo taken from the eastern location. Location lacks any vegetative growth and the vegetative is not representative of surrounding areas, mainly cheatgrass along this portion of the location.