



photo 1: Facing toward the beginning of the access road.



photo 2: Facing west along the access road. The access road has not been reclaimed and there is noxious weed infestation along the road.



photo 3: There is Diffuse and Spotted knapweed (List B noxious weeds) growing along the access road and at the location.



photo 4: There is new growth of Diffuse knapweed throughout the location and access road.



photo 5: Facing northwest toward the location.



photo 6: An electrical utility remains at the southeast side of the location.



photo 7: There is Diffuse and Spotted knapweed (List B noxious weeds) growing throughout the location.



photo 8: There are degraded wattles around the east side of the location.



photo 9: North side of the location facing south.



photo 10: Facing along the northwest side of the location.