



photo 1: Facing southwest along the access road toward the location. There is erosion occurring along the side of the access road.



photo 2: There is noxious weeds (Diffuse knapweed) growing along the access road.



photo 4: Facing east toward the location.



photo 3: There is List B noxious weeds (Diffuse knapweed) found growing throughout the location.



photo 5: East side of the location facing west. Vegetation has not adequately established.



photo 6: There is straw debris left in piles at the west side of the location.



photo 7: Facing east along the south side of the location.



photo 8: South side of the location facing north. There is erosion transporting sediment off location in this area.



photo 9: Facing along the cut slope at the southeast side of the location.



photo 10: There is plastic netting debris along the southeast cut slope.



photo 11: There are signs of erosion along southeast side of the location.



photo 12: Facing toward the nearby undisturbed reference area.