

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2016

Submitted Date:

09/13/2016

Document Number:

684902273**FIELD INSPECTION FORM**

Loc ID 326976 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: 12741 E CALEY STE 142City: CENTENNIAL State: CO Zip: 80111**Findings:**20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Tucker, Lee		rleetuck@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111633	PIT		09/23/1999		-	NICKERSON 4	
246165	WELL	SI	05/31/2015	GW	123-13962	NICKERSON 4	SI

**General Comment:**

[Followup inspection to inspection doc#684901286 in response to form 42 doc#2451452](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	engine oil, methanol, biocide, propane; all adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	agricultural; adequate		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:	adequate		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	pumps - 2 methanol; adequate		
Corrective Action:		Date:	
Type: Ancillary equipment	# 7		
Comment:	containers- 4 biocide, 2 engine oil, 1 propane; adequate		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:	adequate		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	adequate		Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	ajax; adequate		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	adequate		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	adequate		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.576870,-103.916170
Comment:	adequate				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 111633 Type: PIT API Number: - Status:  Insp. Status: Facility ID: 246165 Type: WELL API Number: 123-13962 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SICorrective Action:  Date: **BradenHead**Comment: Bradenhead plumbed to surfaceCorrective Action:  Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: adequate

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: NO Pit ID: 111633 Lat: 40.576466 Long: -103.914186Reference Point: SE Other: \_\_\_\_\_ Length: 10 Width: 15**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Netting:**Netting Type: Mesh Netting Condition: GoodComment: adequate

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: \_\_\_\_\_Comment: produced water pit

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684902273	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3949862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3949862</a>