

# Reclamation Inspection

09/08/2016

Operator: Chandler & Associates

Location ID: 378092

Arapahoe County, CO

NWNW Section 29 T4S R64W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo taken from the southwest corner of the location, facing north. Photo shows large unvegetated portions of the west end of the location caused by erosion.



**Figure 2:** Photo taken from the southwest corner of the location, facing east. Photo shows vegetation over the reclamation area.



**Figure 3:** Photo taken from the southeast corner of the location, facing west. Photo shows vegetation over the reclamation area. Note location has not achieved uniform vegetative cover.



**Figure 4:** Photo taken from the southeast corner of the location, facing north. Photo shows vegetation over the reclamation area. Note location has not achieved uniform vegetative cover.



**Figure 5:** Photo taken from the northeast corner of the location, facing south. Photo shows vegetation over the reclamation area. Note location has not achieved uniform vegetative cover.



**Figure 6:** Photo taken from the northeast corner of the location, facing west. Photo shows vegetation over the reclamation area. Note location has not achieved uniform vegetative cover.



**Figure 7:** Photo taken from the northwest corner of the location, facing south. Note location has not been recontoured or achieved uniform vegetative cover.



**Figure 8:** Photo taken from the northwest corner of the location, facing east. Note location has not achieved uniform vegetative cover.



**Figure 9:** Photo taken from location. Photo shows location has not achieved uniform vegetative cover. 6' measuring stick for reference.



**Figure 10:** Photo shows casing still remaining on location. Note erosion on slope behind casing.



**Figure 11:** Photo taken from the west end of the location, facing west. Photo shows stormwater erosion occurring on slopes. 6' measuring stick for reference.



**Figure 12:** Photo taken from the west end of the location, facing west. Photo shows stormwater erosion occurring on slopes. 6' measuring stick for reference.



**Figure 13:** Photo taken from the southwest end of the location, facing southwest. Photo shows stormwater erosion occurring on slopes. 6' measuring stick for reference.