



photo 1: Facing northwest toward the location.



photo 2: View of vegetation growth at the southeast side of the location. There is little to no vegetation growth in this area.



photo 3: Facing west along the south side of the location (fill slope).



photo 4: There is trash debris in a pile at the northwest side of the location.



photo 5: Northwest side of the location facing southeast.



photo 6: Northwest side of the location facing east toward the cut slope.



photo 7: There is plastic debris along areas of the cut slope.



photo 8: North side of the location facing south.



photo 9: Center of the location facing north.



photo 10: Facing toward the nearby undisturbed reference area.