



photo 1: Facing northwest along the access road toward the location. There is an erosion channel which is developing along the road near the location.



photo 2: Facing northwest toward the location.



photo 3: Facing toward the east side of the location. Vegetation has not adequately established in this area.



photo 4: There is a transplanted tree at the location which is now debris.



photo 5: Center of the location facing southeast.



photo 6: Center of the location facing west.



photo 7: South side of the location facing north.



photo 8: Facing toward the nearby undisturbed reference area.