

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2016

Submitted Date:

09/15/2016

Document Number:

685301374**FIELD INSPECTION FORM**Loc ID 333710 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Tahmahkera, Kerry		MaralexTech@gmail.com	Production Technician
Hughes, Jim		jimo.hughes@state.co.us	
Ohare, Mickey	970-563-4000	amohare@maralexinc.com	President
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Weems, Mark		mark.weems@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265538	WELL	PR	10/15/2003	GW	067-08770	JENNIE ROSE 33-7-3 1	PR
297903	WELL	XX	03/04/2015	LO	067-09619	Jennie Rose 3B	XX

**General Comment:**

Inspection report contains corrective action and comment. See Spills and Equipment Sections of report for additional comment. See link at end of report for path to downloadable pictures.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Produced water actively dripping from wellhead. Area 14' X 7' of ground is saturated with standing small puddles. Observed bubbles in fluid migrating to surface around wellhead casing.			
Corrective Action:	Contact COGCC EPS			Date: 09/14/2016

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Post and Wire.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Natural Gas Motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead - Water is leaking around packing and dripping onto the ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d		Date: 09/16/2016
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Lube Oil Tank on Spill Prevention.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	265538	Type:	WELL	API Number:	067-08770	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	297903	Type:	WELL	API Number:	067-09619	Status:	XX	Insp. Status:	XX

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB):	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301399	Stained soils at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951410</a>
685301400	Spill at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951411">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951411</a>
685301401	Measured length	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951412</a>
685301402	Measured width at widest point	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951413</a>
685301403	Wellhead with spill containment materials wrapped around it	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951414</a>
685301404	Gas escaping from around casing	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951415">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951415</a>