



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Plunger Lift

# 1

corrective date

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
			CENTRALIZED BATTERY		

Comment: [Shared with API 05-123-23852](#)

Corrective Action:

Date:

**Paint**

Condition:

Other (Content):

Other (Capacity):

Other (Type):

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No:

Comment:

Corrective Action:

Date:

**Flaring:**

Type:

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 414222 Type: WELL API Number: 123-30696 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection.</a>	carlilec	09/15/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674004387	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951419">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951419</a>