



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing in the interim reclamation areas. With desirable species such as James gallets (*Pleuraphis jamesii*), penstemon (*Penstemon* sp.), and western wheatgrass (*Pascopyrum smithii*). However portions of the project area are infested with weeds that need to be controlled (see photos below).



Photo 4. View of musk thistles (*Carduus nutans*) in the northwestern corner of the well pad.



Photo 5. View of a cluster of musk thistle rosettes growing along the northern edge of the well pad.



Photo 6. View of infestation of Canada thistle (*Cirsium arvense*) in the southern portion of the project area.



Photo 7. View of silt trap in the western portion of the project area.



Photo 8. View of wattles and hay bales in the northwestern corner in disrepair.



Photo 9. View of wattles in the northeastern corner of the well pad in disrepair.



Photo 10. View of straw wattle on the southwestern edge of the project area that is filled with sediment.