

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2016

Submitted Date:

09/15/2016

Document Number:

681700244

**FIELD INSPECTION FORM**

Loc ID 319644 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 200077  
Name of Operator: CHARLES P DUNNING LLC  
Address: PO BOX 1365  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
DUNNING, CHUCK	303-408-2575	CHUCK.DUNNING@ME.COM	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200657	WELL	PR	11/27/2001	OW	001-06060	JOLLY-PLATTS 2	EI

**General Comment:**

[COGCC Environmental Inspection. See Field Inspection Report #681700239 for related tank battery facility and pit complex.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well sign at southwest corner of pump shed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Overall Good:

**Spills:**

Type	Area	Volume			
Lube Oil	Pump Jack	<= 1 bbl			
Comment:	Oil-stained soil beneath prime mover (inside of pump shed--see photo).				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.			Date:	10/15/2016

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Pipe fence.		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Day tank on northeast side of pumping unit has adequate secondary containment		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 200657 Type: WELL API Number: 001-06060 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700245	Well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951882">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951882</a>
681700246	Oil-stained soil at prime mover	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951883">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3951883</a>