

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2016

Submitted Date:

09/15/2016

Document Number:

673403616

**FIELD INSPECTION FORM**

Loc ID 324630 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10352  
Name of Operator: CM PRODUCTION LLC  
Address: 390 UNION BLVD SUITE 620  
City: LAKEWOOD State: CO Zip: 80228

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212200	WELL	SI	03/25/2013	OW	057-06093	MARGARET SPAULDING 11	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign removed. COGCC emergency contact notices posted.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	COGCC emergency contact notices posted.	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Stained soil at wellhead.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Hazardous energy sources shall be locked out and tagged out per 29 CFR 1910.147 by a qualified person.		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 212200 Type: WELL API Number: 057-06093 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well has been shut in since February 2012 with no MIT.

Corrective Action: Hazardous energy sources shall be locked out and tagged out per 29 CFR 1910.147 by a qualified person.

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Follow up to inspection from 7/1/2016 document number 673403352.</a>	waldrone	09/15/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673403616	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3952180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3952180</a>
673403617	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3952143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3952143</a>